



IMPORTANT

Recommended Repair/Overhaul
procedures call for piston assemblies to be
replaced in **complete engine sets**.

Mixing **new** and **old** piston assemblies in an
engine is **not recommended** due to potential
weight difference that can result in **engine
vibration** and/or **serious damage!**

Pistons supplied in **PAI Engine Kits** have
matched weights to maintain proper engine
balance and **vibration free** operation.

ISO 9001
CERTIFIED



IIF1080 Rev B



IMPORTANTE!

Los procedimientos de Reparación Parcial o de
Reconstrucción de motores recomiendan que
todos los conjuntos de pistón sean reemplazados
en grupos completos.

La mezcla de conjuntos de pistón **nuevos** y
viejos en un motor **no se recomienda** debido a
la **diferencia de peso** potencial entre ellos que
puede causar **vibraciones** y/o **daños severos**
en el motor.

Los pistones suministrados en los **conjuntos
de motor PAI** tienen **pesos similares** para
mantener el balance apropiado del motor

ISO 9001
CERTIFIED



IIF1080 Rev B

