www.paiindustries.com May 2017



Quick Change Trunnion

WORLD TESTED. PERFORMANCE PROVEN.





803832 803833

PAI REF.	REPLACE	DESCRIPTION
803832	Replaces FTB-4712 MAK97QL585	ASSEMBLY, Trunnion Bracket (Trapezoidal Hole Pattern)
803833	Replaces 803830 MAK97QL5119M	ASSEMBLY, Trunnion Bracket (Square Hole Pattern) Space Plate Available for Single Frame/Single Rail
803816	OEM: N/A	Plate, Spacer (Square Hole Pattern)

Interchange Information

(3-1/2" Shafts)

5-1/2 Silaits)

Designed for 32-1/4" frame Width

Advise if your application varies

Model

MR 685S

DM Series

RB Series

MACK APPLICATION, SS44 /SWS57 CAMELBACK SUSPENSIONS

Quick Change Trunnion (QCT) Offers:

EASY INSTALLATION!

Replacement for Original Equipment Mack Stand


Comes Complete with Mounting Hardware

No Removing Body Components, Chassis, Hydraulic Line or Wiring Harness

Heat Treated Alloy Steel

Less R/R Time!





Verify quick change table availability, contact PAI Technical Support at 866.994.3844 with your truck serial number.

RD Series

CH/CV/CX Series