

ATTENTION: ENGINE MECHANIC

Please attach this label to the vehicle steering wheel after Engine/Cylinder rebuild.

ATTENTION: OPERATOR

Your engine has just been rebuilt using genuine PAI components. The first 100 miles (3 hours) are very important in the life of these parts.

For the first 100 miles PAI recommends the following:

1. Do not idle the engine more than 5 minutes at any one time.
2. Operate the engine under moderate load at 75% of rated RPM as much as possible.
3. Do not operate the engine at maximum rated RPM during first 100 miles.

- Following these guidelines will contribute to the life of your engine.



Atención: Mecánico del Motor

Favor de asegurar esta etiqueta al volante/timón después de reparar el motor/ cilindros

Atención: Operador

El motor ha sido reconstruido usando repuestos genuinos PAI. Las primeras 100 millas (160 Km, 3 horas) son muy importantes en la durabilidad de estas piezas. Por las primeras 100 millas (160 Km.).

PAI recomienda lo siguiente:

1. No opere el motor en baja por más de 5 minutos seguidos.
2. Opere el motor bajo carga moderada a 75% de las revoluciones por minuto recomendadas tanto como sea posible.
3. No opere el motor al máximo de revoluciones por minuto durante las primeras 100 millas (160Km)

- El seguir estas recomendaciones contribuirá a la vida del motor

