



## 805025 FLYWHEEL HOUSING UPDATE

**ISO 9001**  
CERTIFIED

This flywheel housing has been revised by the OE. Originally the transmission was mounted using (12) 10mm bolts/washers. Current housing design mounts the transmission using (12) 7/16-14 bolts and (12) hardened washers.

New transmission mounting bolts and hardened washers are enclosed with the PAI 805025 housing, and must be used to mount the transmission assembly.

840028 - 12 Bolts

841250 - 12 washers

IIF1226



## Actualización de la Carcasa del Volante 805025

**ISO 9001**  
CERTIFIED

Esta carcasa del volante ha sido revisada por el Fabricante del Camión. Originalmente la caja de cambios/transmisión se montaba utilizando 12 tornillos y arandelas de 10 mm. El diseño actual de la carcasa monta la caja/transmisión utilizando 12 tornillos 7/16"-14 y 12 arandelas endurecidas (tratadas).

Estos tornillos y arandelas endurecidas nuevas para montar la caja/transmisión están incluidos con la carcasa PAI 805025, y deben ser utilizados para montar la caja/transmisión.

840028- 12 tornillos

841250-12 arandelas

IIF1226

